







TABLE 6							
-No. OF ROWS	Ø "P"	"N"					"S"
		10 Pos.	20 Pos.	30 Pos.	-40 Pos	-50 Pos.	3
-04	4.25 [0.167]	4.80 [0.189]	8.80 [0.346]	12.80 [0.504]	16.80 [0.661]	20.80 [0.819]	.025 [0.001]
-06	6.25 [0.246]	3.80 [0.149]	7.80 [0.307]	11.80 [0.464]	15.80 [0.622]	19.80 [0.779]	.026 [0.001]
-08 (SEE NOTE 11)	8.25 [0.325]	2.80 [0.110]	6.80 [0.268]	10.80 [0.425]	14.80 [0.582]	18.80 [0.740]	.025 [0.001]
-10 (SEE NOTE 11)	10.26 [0.404]	2.80 [0.110]	5.79 [0.228]	9.79 [0.385]	13.79 0.543]	17.79 [0.700]	.020 [0.001]

 \Box = FOR 10 POSITION ONLY, ϕ "P" = 8.25 [0.325], "S" = 1.025 [0.040]



