

PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

PCN #17-003

NOTIFICATION DATE: January 23, 2017

MODEL(S) AFFECTED:

DSN, JTOS, KSN, MOS, POS, ROS, RSN, SOS, SSG, ZOS, ZSN, ZX95
(See attached list for specific models)

EXTENT OF CHANGE:

Models listed will continue to be manufactured with their existing Bills of Materials, as long as possible, based on customers' advisement of potential requirements.

EFFECT OF CHANGE:

Listed models are under review for redesign with goal of repeating original performance. Last time buys of the current design are being offered until May 1, 2017, to existing customers in order to extend availability. Redesign may be considered based on customer demand.

REASON FOR CHANGE:

End of life notification received from supplier of critical internal components

EFFECTIVE DATE OF CHANGE:

Immediate

ATTACHMENTS:

List of Models

QUESTIONS?

[PLEASE CONTACT US.](#)

PRODUCT CHANGE NOTICE PCN Form (D4-E000-73)

Attachment to: **PCN#17-003**

** List of Affected Models **				
DSN-1500A-1119+	JTOS-2700V+	KSN-395A-1C19+	POS-200+	ROS-1100V+
DSN-1750A-219+	JTOS-300	KSN-409A-219+	POS-2000A+	ROS-1120-119+
DSN-2050A-119+	JTOS-300+	KSN-490A-1C19+	POS-200P+	ROS-1150-519+
DSN-2300A-1119+	JTOS-3000+	KSN-529A-119+	POS-25+	ROS-1185-119+
DSN-2620A-119+	JTOS-300P+	KSN-558A-119+	POS-300+	ROS-1200W+
DSN-2700A-1119+	JTOS-400+	KSN-675A-2C19+	POS-300P+	ROS-1215-119+
DSN-3019A-119+	JTOS-400P+	KSN-700A-1C19+	POS-400+	ROS-1250W-119+
JCOS-820WLN	JTOS-50+	KSN-700A-3C19+	POS-50+	ROS-1270-1PH19+
JTOS-100	JTOS-50P+	KSN-800A-119+	POS-500W+	ROS-1275+
JTOS-100+	JTOS-535+	KSN-864A-1C19+	POS-50P+	ROS-1300+
JTOS-1000W+	JTOS-535P+	KSN-900A-119+	POS-535+	ROS-1330-1PH19+
JTOS-100P+	JTOS-75+	MOS-114+	POS-535P+	ROS-1357+
JTOS-1025+	JTOS-75P+	MOS-1400-119+	POS-75+	ROS-1410+
JTOS-1025P	JTOS-765+	MOS-1826PV+	POS-75P+	ROS-1435PV+
JTOS-1300+	JTOS-765P+	MOS-810-119+	POS-765+	ROS-1455+
JTOS-150	JTOS-850VW+	MOS-868-119+	POS-800W+	ROS-1480-219+
JTOS-150+	K-JTOS-3+	MOS-924-119+	POS-900W+	ROS-148-119+
JTOS-150P+	K-POS-1+	POS-100+	ROS-100+	ROS-150+
JTOS-1550+	K-POS-2+	POS-1000W+	ROS-1000PV+	ROS-1500+
JTOS-1910+	K-POS-3+	POS-100P+	ROS-1000V+	ROS-1505-519+
JTOS-200+	KSN-1145A-119+	POS-1025+	ROS-1005-119+	ROS-1540-419+
JTOS-2000+	KSN-1682A-119+	POS-1060+	ROS-1012-1PH19+	ROS-1560-1PH19+
JTOS-200P+	KSN-2457A-1C19+	POS-1400A+	ROS-102-919+	ROS-1600PV+
JTOS-25+	KSN-3500A-119+	POS-150+	ROS-1034-119+	ROS-1600W+
	KSN-3700A+	POS-150P+	ROS-1090-219+	ROS-1605PV+

PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

Attachment to: **PCN#17-003****** List of Affected Models ****

ROS-1645W-119+	ROS-2500-2119+	ROS-4403-119+	ROS-625-119+	ROS-780+
ROS-1700W+	ROS-258-119+	ROS-445+	ROS-625-219+	ROS-800-1019+
ROS-1707-119+	ROS-285PV+	ROS-4540-119+	ROS-630+	ROS-808+
ROS-1720+	ROS-300+	ROS-470+	ROS-638+	ROS-810+
ROS-1750-1219+	ROS-3050-819+	ROS-470-319+	ROS-645+	ROS-810LN+
ROS-1770-1PH19+	ROS-310-419+	ROS-470-519+	ROS-660PV+	ROS-824-119+
ROS-1800+	ROS-310-519+	ROS-470-819+	ROS-665+	ROS-835+
ROS-1800+	ROS-3200-419+	ROS-480+	ROS-675-219+	ROS-850+
ROS-1862-119+	ROS-3250-519+	ROS-485+	ROS-680+	ROS-850-719+
ROS-1900+	ROS-3360+	ROS-485-119+	ROS-690+	ROS-850W-119+
ROS-1900V+	ROS-3360-319+	ROS-498-119+	ROS-694-119+	ROS-860-319+
ROS-190-219+	ROS-3550+	ROS-505+	ROS-700+	ROS-86-119+
ROS-200+	ROS-355-219+	ROS-5150-119+	ROS-70-219+	ROS-870+
ROS-200-619+	ROS-3555+	ROS-520+	ROS-705-219+	ROS-892-119+
ROS-2050-719+	ROS-3600-619+	ROS-5200C-119+	ROS-71-119+	ROS-900-519+
ROS-205PV+	ROS-365-119+	ROS-530+	ROS-715+	ROS-900PV+
ROS-2082-119+	ROS-368-119+	ROS-535+	ROS-730+	ROS-950-219+
ROS-2150VW+	ROS-369-319+	ROS-540+	ROS-730-319+	ROS-95-419+
ROS-2230-119+	ROS-3800+	ROS-5400+	ROS-740PV+	ROS-960-419+
ROS-2310+	ROS-3900-419+	ROS-550+	ROS-745+	ROS-960PV+
ROS-2350+	ROS-400+	ROS-550A+	ROS-750+	ROS-995-119+
ROS-2390+	ROS-400-1119+	ROS-550PV+	ROS-755+	RSN-1618AF-119+
ROS-2432-119+	ROS-404-219+	ROS-570+	ROS-765+	RSN-749AF+
ROS-2490+	ROS-4077-119+	ROS-585+	ROS-766+	SOS-1230-119+
ROS-2500+	ROS-425-319+	ROS-610-319+	ROS-769-1G19+	SSG-4000LH

PRODUCT CHANGE NOTICE PCN Form (D4-E000-73)

Attachment to: **PCN#17-003**

** List of Affected Models **			
ZOS-100+	ZX95-1740-S+	ZX95-4403-S+	ZX95-694-S+
ZOS-1025+	ZX95-1900V-S+	ZX95-445-S+	ZX95-700-S+
ZOS-150+	ZX95-200-S+	ZX95-4540-S+	ZX95-715-S+
ZOS-200+	ZX95-2050-S+	ZX95-470A-S+	ZX95-730A-S+
ZOS-300+	ZX95-2150VW-S+	ZX95-470-S+	ZX95-730-S+
ZOS-400+	ZX95-2390-S+	ZX95-485A-S+	ZX95-755-S+
ZOS-50+	ZX95-2490-S+	ZX95-485-S+	ZX95-765-S+
ZOS-535+	ZX95-2500B-S+	ZX95-498-S+	ZX95-766-S+
ZOS-75+	ZX95-2500-S+	ZX95-505-S+	ZX95-780-S+
ZOS-765+	ZX95-258-S+	ZX95-5150-S+	ZX95-800A-S+
ZSN-3700AC+	ZX95-310A-S+	ZX95-5200C-S+	ZX95-808-S+
ZX95-1005-S+	ZX95-310-S+	ZX95-520-S+	ZX95-810-S+
ZX95-100-S	ZX95-3250-S+	ZX95-530-S+	ZX95-835-S+
ZX95-100-S+	ZX95-3360A-S+	ZX95-535-S+	ZX95-850-S+
ZX95-1012-S+	ZX95-3360-S+	ZX95-5400-S+	ZX95-850W-S+
ZX95-1034-S+	ZX95-3550-S+	ZX95-540-S+	ZX95-860-S+
ZX95-1185-S+	ZX95-3555-S+	ZX95-550A-S+	ZX95-868-S+
ZX95-1200W-S+	ZX95-3600-S+	ZX95-550-S+	ZX95-870-S+
ZX95-1300-S+	ZX95-365-S+	ZX95-585-S+	ZX95-900-S+
ZX95-1410-S+	ZX95-368-S+	ZX95-610-S+	ZX95-924A-S+
ZX95-1480-S+	ZX95-369-S+	ZX95-625A-S+	
ZX95-148-S+	ZX95-3800-S+	ZX95-625-S+	
ZX95-1505-S+	ZX95-3900A-S+	ZX95-638-S+	
ZX95-1600W-S+	ZX95-400-S+	ZX95-665-S+	
ZX95-1700W-S+	ZX95-4077-S+	ZX95-675-S+	